PRINTED: 10/03/2012 FORM APPROVED

Indiana State Department of Health

AND DUAN OF CODDECTION		(X1) PROVIDER/SUPPLIER/C IDENTIFICATION NUMBI			(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		(X3) DATE SURVEY COMPLETED	
000235				B. WING		09/18/2012		
NAME OF PROVIDER OR SUPPLIER			STREET ADDRE	TREET ADDRESS, CITY, STATE, ZIP CODE				
LIFE CARE CENTER OF LAGRANGE			0770 N 075 E LAGRANGE, IN 46761					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE	
K 000	00 INITIAL COMMENTS			K 000				
	A Quality Assurance Walk-thru Survey was conducted by the Indiana State Department of Health.							
	Survey Date: 09/18/12							
	Facility Number: 000235 Provider Number: 155343 AIM Number: 100267740							
	Surveyor: Robert Sutton, Life Safety Code Specialist Trainee							
	At this Quality Assurance Walk-thru survey, Life Care Center of LaGrange was found in compliance with 410 IAC 16.2-3.1-19(ff).							
	This one story facility was determined to be of Type V (111) construction and fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and areas open to the corridors with battery operated smoke detectors in the resident rooms. The facility has a capacity of 100 and had a census of 72 at the time of this visit.							
	The facility was in compliance with state law in regard to sprinkler coverage and smoke detector coverage.							
	were sprinklered and	ents have customary a all areas providing faci ered, except one detac y storage.	lity					
		bert Booher, Life Safet cal Surveyor on 10/02/						

Indiana State Department of Health

TITLE (X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE